


22-DC Machine Construction

ECEGR 450
Electromechanical Energy Conversion




Overview

- Introduction
- Physical Construction
- Armature Winding

Dr. Louie

2




DC Generators

- Magnetic flux is established by poles within the generator **stator** (stationary part)
 - flux is produced by permanent magnets or field windings (electromagnets)
- emf is induced in a coil that rotates called the **armature**

In AC generators, the emf is induced in a stationary coil. The term "armature" refers to the windings in which the emf is induced and current flows when connected to a load.


Dr. Louie

3



Physical Construction


- Main Components:
 - Stator
 - Field Winding
 - Armature
 - Commutator (not shown)
 - Brushes (not shown)
- See book Fig 5.1, 5.2 for more detailed drawings
- DC motors have same construction



cross section


Dr. Louie

4



Stator


- Provides mechanical support
- Yoke
 - Highly permeable material
- Poles
 - Mounted inside the yoke



cross section


Dr. Louie

5



Field Winding

- Polarity alternates N, S
- Either PM or coils:
 - Can be wound in series, parallel (shunt), or both (compound)
 - Advantage: control the amount of flux by controlling the current
 - Disadvantage: current flowing through the windings create losses



cross section

Dr. Louie

6

Armature

- Rotates in a dc machine
- Made of highly permeable material
- Armature coils usually made from copper with insulation
- Circular cross section with slots to accommodate the armature coils (armature windings)
- Armature winding can be lap or wave wound

armature slot

armature winding

cross section

Dr. Louie 7

Commutator

- Key component of DC machine
- Rotates with rotor
- Functions like a mechanical rectifier
- Armature windings are connected to it
 - Configuration depends on whether lap or wave winding was used in the armature
 - Allows for connection of generator with external circuit through the brushes

Location of commutator

Dr. Louie 8

Commutator

- Stationary brushes connect machine to circuit through commutator
- 2 or more commutator segments (odd numbers possible)
- Commutator rotates with rotor
- Segments are insulated from each other
- One or more coils connected to each segment

Dr. Louie 9

Brushes

- Connect the rotating commutator to the circuit
- Usually made of carbon or carbon-based mixture
- Spring-loaded to ensure good connection with commutator
- Require maintenance and replacement

Source://www.electrotechnik.net/2011/02/electric-brushes.html

Dr. Louie 10

Commutator and Brushes

simplified 2-pole stator shown

Recall: current into paper under N pole for CW rotation

Dr. Louie 11

Armature Winding

Recall: $e = \Phi_p \omega \sin \theta$

$\theta = 0^\circ, V_{ab} = 0$
zero emf and segments are shorted


$\theta = 45^\circ, V_{ab} = 0.7$

$\theta = 90^\circ, V_{ab} = 1.0$

Dr. Louie 12

Armature


- Output voltage in dc generator with single coil
- Large ripple
- Pulsating current, torque, power
- How can ripple be reduced?
- How can the induced voltage be increased?



Dr. Louie 13

Armature Winding


- Consider 4 armature coils
 - Red, blue, green, purple
- Each coil:
 - Has two ends
 - Full pole pitch
- Indicate the polarity of the induced current in each conductor if each coil is connected to an external circuit



Dr. Louie 14

Armature Winding



- Current in conductors near N pole flow into paper
- Current in conductors near S pole flow out of paper



Dr. Louie 15

Armature Winding


- Current flows from segment 1:
 - into purple coil by N pole
 - out of purple coil by S pole
 - into segment 2
 - into red coil by N pole
 - out of red coil by S pole
 - into segment 3

Dr. Louie 16

Armature Winding

- Draw coil-to-segment connections to make blue and green coils in series
- Do not short any coil (e.g. connect both ends of red coil to same segment)
- Respect polarity of current




Current will flow into "x" and out of ●

Dr. Louie 17

Armature Winding

- Current flows from segment 1:
 - into blue coil by N pole
 - out of blue coil by S pole
 - into segment 4
 - into green coil by N pole
 - out of green coil by S pole
 - into segment 3



Dr. Louie 18

Armature Winding

- Let brushes be positioned along N-S axis
- Two parallel paths
- Each path has two series coils

$\theta = 45^\circ$

$$|e_p| = |e_g| = |\Phi_p \omega \sin \theta|$$

$$|e_r| = |e_b| = |\Phi_p \omega \sin(\theta - 90^\circ)|$$

$$v_{ab} = |e_p| + |e_r| = |e_g| + |e_b|$$

Polarity already accounted for.

Dr. Louie 19

Armature Winding

$\theta = 90^\circ$

$$|e_p| = |e_g| = \Phi_p \omega \sin \theta = \Phi_p \omega$$

$$|e_r| = |e_b| = \Phi_p \omega \sin(\theta - 90^\circ) = 0$$

$$v_{ab} = |e_p| + |e_r| = |e_g| + |e_b| = \Phi_p \omega$$

shorted windings have 0 emf

Dr. Louie 20

Armature Winding

- Effects of adding armature windings
 - Reduce ripple
 - Higher peak voltage
 - Higher average voltage

4 coils: black
1 coil: red

Dr. Louie 21

Armature Windings

4 pole, 4 armature winding machine

Dr. Louie 22

Armature Windings

4 pole, 4 armature winding machine

No current flow, $V_{ab} = 0$

Dr. Louie 23

Lap Winding

- Discussed winding method known as *Lap Winding*
- Very common
- Used in low-voltage, high-current machines
 - High number of parallel paths for current
 - Low number of coils in series
- Ends of a coil are connected to adjacent segments on the commutator
 - Number of commutator segments equals the number of armature slots

Dr. Louie 24



Lap Winding

- Number of brushes = number of parallel paths = number of poles
 - Must be even number
- Number of segments = number of armature windings
 - Possible for odd number of armature windings

Dr. Louise

25



Wave Winding

- Used in high-voltage, low-current machines
 - Connect armature windings in series to obtain high voltage
 - Those under N pole are connected together
 - Those under S pole are connected together
 - Armature windings are connected almost 360° electrical apart (can be more, can be less)
- Always 2 brushes
- Number of commutator segments = number of slots
- Windings are the same as in Lap wound machines, but the commutator pitch is different

Dr. Louise

26



Armature Winding

- Recall that maximum emf occurs in a full-pitch coil (180° electrical)
- May not be easy to wind using full-pitch, so fractional pitch may be used
 - Reduces emf by a value known as the pitch factor

Dr. Louise

27



Example

How many brushes and commutator segments does a 6-pole dc machine with 31 armature windings have?

Dr. Louise

28



Example

How many brushes and commutator segments does a 6-pole dc machine with 31 armature windings have?

6 brushes

31 commutator segments

Dr. Louise

29



Summary

- DC machines are composed of: stators, rotors, field windings (or PMs), armature windings, brushes and commutator
- Increasing # of armature winding improves output waveform
- Armature windings may be lap or wave wound
- Lap winding: # of poles = # of brushes
of armature windings = # of commutator segments
 - Winding ends connected to adjacent segments

Dr. Louise

30